



*Damage inspection*

***Saltash Town Council /  
Jubilee Pontoon***

*for Woodgate & Clark*

*Your ref: 9476808A*

*Surveyor: Pete Crispin*

*Date of inspection: 15 January 2025*

*Date of report: 21 January 2025*

*Inspection location: Jubilee Pontoon, Jubilee Green, Saltash, Cornwall, PL12 6JD*

Pete Crispin  
Mobile: +44 (0)7956 102372  
[pete@crispinmarine.com](mailto:pete@crispinmarine.com)  
[www.crispinmarine.com](http://www.crispinmarine.com)

# *‘Jubilee Pontoon’*



## **Contents**

Introduction		Page 3
Inspection limitations		Page 3
Key people		Page 3
Background and incident		Page 4
Inspection and damage		Page 4
Cause		Page 5
Maintenance		Page 5
Costs		Page 5
Conclusion		Page 5
Pictures		Page 6
Notices		Page 15
Appendix I	Storm Damage Report	Separate
Appendix II	Diver report: 2015	Separate
Appendix III	Divers thickness readings: 2015	Separate
Appendix IV	Annual survey report: 2021	Separate
Appendix V	Docking estimate	Separate

## Introduction

Instructions were received from Jane Gambell-Pogson of Woodgate & Clark on 30 December 2024 to investigate a claim made by the insured, Saltash Town Council, for storm damage to the Jubilee Pontoon.

The pontoon has the following specification, as found on the day and supplied by the insured:

Builder / model:	Docking Solutions Ltd (no longer trading)
Arrangement:	Two main pontoons in a T-shape, with two finger pontoons on each side
Walkway pontoon:	30m x 3m x 1.2m
Waterfront pontoon:	20m x 4m x 1.2m
Date built:	c. 2003
Capacity:	10 x permanent berths and 1x emergency
Construction:	Steel floats with galvanised frame and composite decking / galvanised brow with timber decking
Sum insured:	H&M: £250,000 / Excess: £500

## Inspection limitations

1. The pontoon arrangement was seen afloat. Some of the damaged areas were accessible but it could not be confirmed that all were.
2. The insured's staff attended to give access and assistance if needed. The insured's preferred repairer was contacted.
3. No part of the pontoon was dismantled, no bolts or screws were removed for inspection and no linings or ballast were removed. No invasive inspections were carried out.
4. Although inspected using best professional practice, it is possible that there may be additional faults to those that were found.

## Key people

Ian Bovis: Service Delivery Manager, Saltash Town Council. Referred to as the *insured* in this report.

Graham Chapman: Project Manager at Underhill Engineering (UK) Ltd. Referred to as the *repairer* in this report.

## **1. Background and incident**

- 1.1 The insured claims that the pontoon was damaged in Storm Darragh on 6 / 7 December 2024.
- 1.2 The repairer attended and issued a Storm Damage Survey Report, Appendix I, on 30 December 2024.
- 1.3 The insured manages and maintains the Jubilee Pontoon which is on the River Tamar.

## **2 Inspection and damage**

### **2.1 At the inspection, the following was found:**

- The pontoon arrangement is accessed using a galvanised steel brow from the shore. The gate to it had been closed off to the public because of the damage.
- The brow extends over and in parallel with one of two main pontoons and has two, small finger pontoons on each side. This is referred to as the walkway pontoon in this report. The other main pontoon section runs at 90 degrees to the brow and pontoon below, creating a T shape. This is referred to as the waterfront pontoon.

### **2.2 The following damage was noted:**

- The damage starts where the two main pontoon sections join, which is at the end of the brow. The decking boards have been removed since the repairers report, giving better access to the connections, supports and floats.
- On the walkway pontoon, five angled deck board supports, made from galvanised steel have become detached from the frame structure.
- Welded brackets attached to the floats beneath have snapped. There is some localised corrosion to the floats which may have contributed.
- Where these brackets are attached to the frame structure, the frames were found to have snapped in two locations.
- The connections between the two pontoons have sheared. It was noted that nuts and bolts were severely corroded in these locations. One bolt has clearly been moving and has ovalled its opening.
- The side sections from the walkway pontoon are damaged where they meet the waterfront pontoon section. Boards are out of alignment which indicates possible twisting.
- The repairers report states finding damage between the walkway and finger pontoons, but this was not immediately visible at the inspection. It is difficult to confirm with the deck boards in place but it is possible that there is some damage.
- On the waterfront pontoon section, that forming the top of the T, the longitudinal and transverse boards have risen where it meets the other main pontoon and again, further along on the left-hand side over a length of around 1m. The timber boards mounted as fendering have also been damaged. This also indicates potential twisting to the frame beneath.

### **2.3 The following non-incident related issues were found:**

- The floats, which support the pontoon arrangement are showing signs of fouling at the waterline and below. It was also noted at a previous visit that raw sewage can gather in this area.

- Areas of the floats are showing signs of corrosion.
- The four piles, used to hold the pontoon arrangement in position and to allow it to move with the tide, are corroded.
- The roller arrangement that allows the brow to move on the pontoon has worn.
- On the finger pontoon for berth 2, the timber fendering has broken.
- Water is held on top of the brow pontoon. It appears to have no drainage in this location which means that there is a greater chance of corrosion developing.

### **3 Cause**

- 3.1 There is damage caused to the pontoons that is a result of the storm. However, there are maintenance issues that need to be addressed and require the pontoon to be docked.

### **4 Maintenance**

- 4.1 Maintenance records were requested:

- The last ultrasonic thickness test of the floats was carried out in June 2015 by divers. This means the pontoon was not removed from the water. Their report states an assumed original thickness of 8mm with findings showing this had thinned to 6.0mm and below in the majority of areas. Appendices II / III.
- The repairer was providing annual in-water condition reports, but the last appears to have been done on 21 January 2021. Appendix IV.
- The repairer was contacted. He confirmed that the pontoon was last out of the water for maintenance in 2017. He agreed that it was overdue lifting for maintenance purposes.
- A steel commercial vessel operated to Class, would have to be removed from the water twice in every five year period for inspection and maintenance. This is good practice. Depending on vessel type, steel leisure vessels are advised to be lifted every 3 to 5 years. This pontoon has been in the water for 7 to 8 years.

### **5 Costs**

- 5.1 The repairer has provided a cost for preparation and docking only of £26,450. See Appendix V. No repairs have been included. Docking is necessary for the maintenance works and to assess the damage.
- 5.2 The welding works necessary could not be done in the water. Further, removing the deck boards with the pontoon in position to establish the extent of the damage is not considered safe practice due to the fast tidal waters on the Tamar.
- 5.3 It is recommended that the cost for docking is for the insureds account. Following the scope of works given in Appendix V, an assessment of incident related damage and the repair costs can be given.

### **6 Conclusion**

The pontoon has been damaged in the storm but no repair estimate has been provided. It needs to be lifted and assessed to determine the works needed. However, the pontoon is well overdue docking for maintenance. Because of this, the preparatory, towing and inspection cost of £26,450 is advised as being for the insureds account.

A second inspection may be necessary when the damage is accessible.

A handwritten signature in black ink, appearing to read 'Pete Crispin', with a stylized, cursive script.

Pete Crispin  
MRINA, MIMarEST, MIIMS  
[www.crispinmarine.com](http://www.crispinmarine.com)





Entrance to Jubilee Pontoon



Brow to pontoon





Damage at end of walkway pontoon



Damage at end of walkway pontoon





Corroded bolts on waterside pontoon join



Broken side section on walkway pontoon






Broken float frame on walkway pontoon. Note the corrosion



Broken side section on the other side of the pontoon.





Boards raised, indicating twist, on waterside pontoon



Finger pontoon links look unaffected but should be checked





Brow roller



Pad needs securing





Pad needs replacing



Water in top of walkway pontoon





Walkway pontoon fouling



Pile corrosion

## **Notices**

### **Data Protection**

The information contained in this report is the intellectual property of Crispin Marine Ltd. This document contains confidential information that is legally privileged and is attended for the use of the addressee only. All information contained herein is covered by the EU Data Protection Directive (96/46/EC)

### **Copyright**

This report, the international copyright of which is vested in Crispin Marine Ltd, is confidential to the named client and non-transferable. It must not be copied, reproduced, kept in any data bank, stored in any retrieval system or transmitted in any form or by any means whatsoever or otherwise or given or sold to any third party without the prior written consent of the copyright holder.

### **Disclaimer**

Every effort has been made to ensure the accuracy of the information presented within this report. The report is issued in good faith as a statement of facts, ascertained at the time of the survey, during which due diligence and reasonable skill were exercised and reasonable care taken, using common professional practice and where available published guidelines or codes such as those published by the International Institute of Marine Surveyors.

The vessel and equipment were not being assessed for design, suitability for any particular purpose or compliance with any particular and specific set of rules, regulations or standard.

### **Terms and Conditions**

All work is carried out under the standard terms and conditions for the supply of advice and services of Crispin Marine Ltd.

### **Law and jurisdiction**

This document is to be construed under English Law and English Law shall be used in interpreting the document and for resolving all claims or disputes arising out of or connected with the document.

### **Limitation of liability**

This survey is carried out on the express understanding that Crispin Marine Ltd is legally liable to the above-named client only and not to any subsequent holder of this report or to any third party.