

## **QUOTE COMPANY A**

Good Morning

Thank you for inviting us to quote for the flooring at the above property and meeting Chris on Saturday.

The corridor at the end of the building and the waiting/cafe area would be ok to have the

Forbo R11 product fitted in those areas.

Unfortunately we could not recommend that product in the main events area.

Two reasons - the crack in the flooring has not improved since we last saw it and there

has been a silicon type product installation attempt in the cracking which is already pulling from the edges.

This would indicate that the original screed is far too thin for that type of repair.

Secondly the crack is still moving and looks as though it is deteriorating the longer the area is left

exposed. If the R11 was fitted in that area it would need to have a gap left around the cracked areas

This option would look unsightly and unprofessional.

The only viable option to cover the floor in the main area would be a commercial carpet tile

of which there are many colours and designs available.

We have just done the Ashtorpe Rock flooring with tiles and it looks superb.

We can quote on that basis if you wish

Kind regards

**End**