

## Appendix A to E

### Appendix A:

Some winter pathway clearance pictures. SDGA's using our departmental Kerstan mechanical sweeper and hand tools to keep the site weed free and looking clean and presentable.



**Appendix B:**

Photographs showing the appointed tree surgeon carrying out maintenance works to the large ash tree identified in the recent site tree survey as posing a high risk to visitors and to the memorial located underneath.





**End Of Appendices Pictures and information notes.**