


Service Delivery Team – Works Carried Out

Pillmere Walkways – 8th September 2026

Before



After




Library – 9th September 2026



Pillmere – Honeysuckle Play Park and footpaths 9th September 2026





Churchtown Cemetery – 10th September 2026

Before

After



Waterside – 11th September 2026



Brunel Bust – 11th September 2026



Cornish Cross – 14th September 2026

Before	After
	

Badgers Walk – 14th September 2026

Before	After
 	 

Silver Street – 14th September 2026



Trematon Pound – 15th September 2026



Roundabouts – 15th September 2026

Before	After
	
	
	

Grassmere Play Park – 15th September 2026


Before	After
	

Churchtown – 16th September 2026

Before



After




Ashton Way Play Park – 17th September 2026

Before	After
	
	

Elwell Woods – 17th September 2026


Before	After
	



St Stephens Cemetery – 21st September 2026



St Stephens Cemetery – 22nd September 2026



Beating the Bounds – Boundary Stone 1 – 24th September 2026



Beating the Bounds – Boundary Stone 2 – 24th September 2026

Before	After
	

Beating the Bounds – Boundary Stone 3 – 24th September 2026

Before	After
	

Beating the Bounds – Boundary Stone 4 – 24th September 2026

Before	After
	

Beating the Bounds – Boundary Stone 5 – 24th September 2026

Before	After
	

Beating the Bounds – Boundary Stone 6 – 24th September 2026

Before	After
	

Huntley Gardens – 25th September 2026



Before



After



Waterside – 1st October 2026

Before	After
 Two photographs showing the 'Before' state. The top photo shows a paved pathway curving along a body of water, bordered by a black metal railing with decorative finials. To the left is a grassy area with a tree and orange traffic cones. The bottom photo shows a close-up of a stone wall made of rough-hewn blocks, with a paved path running alongside it. The water and a bridge are visible in the background.	 Two photographs showing the 'After' state. The top photo is identical to the 'Before' top photo. The bottom photo is identical to the 'Before' bottom photo, showing the stone wall and paved path.


Pillmere – 5th October 2026

Before	After
 A photograph showing a paved pathway leading towards a grassy area with a metal railing. In the background, there are dense trees and a clear blue sky.	 A photograph showing the same paved pathway and grassy area as the 'Before' photo, but with a slightly different perspective or lighting, showing the same scene after a change.



Ashton Way Play Park – 5th October 2026

Before



After



Ashton Way – 5th October 2026



Pillmere Paths – 6th October 2026

