

<b>Client Name:</b> Saltash Town Council The Guildhall, Lower Fore Street Saltash PL12 6JX	<b>Site Address:</b> Saltash Library and Information Service Callington Road Saltash PL12 6DX
--	---

<b>Client Order Number</b>		<b>Primary Contact</b>	Rachel Ackland
<b>Reference</b>	ENT/13626	<b>Job Type</b>	Maintenance


<b>Job Detail</b>
-------------------


Engineers to attend site to carry out the service inspection of all quoted assets.  
Engineers to complete condition and compliance reports for all assets serviced.

<b>Engineer Comments</b>
--------------------------

Attended site, signed in, carried out maintenance work, doors left in full working order.  
  
Complete.

<b>Parts Used/Required</b>
----------------------------

<b>Date:</b>	28/07/2023
<b>Start Time:</b>	11:46
<b>Finish Time:</b>	12:46
<b>Travel Time</b>	
<b>Total:</b>	
<b>Engineer's Signature:</b>	

<b>Customer Signature:</b>	
<b>Customer Name:</b>	Shaun Webber

## Equipment Condition & Compliance (Summary Report)

Asset Number	Product Location	Product Type	Status
08816	Main entrance inner	Automatic Door	Healthy No Action
08817	Main Entrance outer	Automatic Door	Healthy No Action



## Automatic Door Certification

<b>Client Name:</b> Saltash Town Council The Guildhall, Lower Fore Street Saltash PL12 6JX	<b>Site Address:</b> Saltash Library and Information Service Callington Road Saltash PL12 6DX
--	---

<b>Job Type</b>	Maintenance	<b>Manufacturer</b>	Kone uni drive
<b>Product Type</b>	Automatic Door	<b>Asset Number</b>	08817
<b>Product Location</b>	Main Entrance outer		

Asset Information	
Asset Type	Double Sliding
Electrical Safety	
Are all of the electrical elements of this product Safe & Compliant?	Pass
Functional Tests & Settings	
Are all Radar Distances correct?	Pass
All Safety Box tests carried out?	Pass
Opening, Holding & Closing time correct?	Pass
Door/s operate as designed?	Pass
Hazards	
All Finger, Barrier, Pocket Guards in place?	Pass
All correct signage in place?	Pass
System operates correctly in the event of an emergency?	Pass
Dynamic Forces (Newtons) compliant?	Pass
Structural Integrity	
All Door & Operator fixings secure and intact?	Pass
Engineer Comments	
General Comments	Maintenance work carried out, door in full working order.

<b>Date &amp; Time</b>	28/07/2023 01:09	<b>Engineer's Signature</b>	
------------------------	------------------	-----------------------------	---

<b>Safety Critical</b>	<b>Further Works Required</b>	<b>Healthy No Action</b>	✓
------------------------	-------------------------------	--------------------------	---

## Automatic Door Certification

<b>Client Name:</b> Saltash Town Council The Guildhall, Lower Fore Street Saltash PL12 6JX	<b>Site Address:</b> Saltash Library and Information Service Callington Road Saltash PL12 6DX
--	---

<b>Job Type</b>	Maintenance	<b>Manufacturer</b>	Dorma
<b>Product Type</b>	Automatic Door	<b>Asset Number</b>	08816
<b>Product Location</b>	Main entrance inner		

Asset Information	
Asset Type	Single Swing
Electrical Safety	
Are all of the electrical elements of this product Safe & Compliant?	Pass
Functional Tests & Settings	
Are all Radar Distances correct?	Pass
All Safety Box tests carried out?	Pass
Opening, Holding & Closing time correct?	Pass
Door/s operate as designed?	Pass
Hazards	
All Finger, Barrier, Pocket Guards in place?	Pass
All correct signage in place?	Pass
System operates correctly in the event of an emergency?	Pass
Dynamic Forces (Newtons) compliant?	N/A
Structural Integrity	
All Door & Operator fixings secure and intact?	Pass
Engineer Comments	
General Comments	Maintenance work carried out, door in full working order.

<b>Date &amp; Time</b>	28/07/2023 01:06	<b>Engineer's Signature</b>	
------------------------	------------------	-----------------------------	--

<b>Safety Critical</b>	<b>Further Works Required</b>	<b>Healthy No Action</b>	✓
------------------------	-------------------------------	--------------------------	---